

## **ETOBICOKE CREEK SIGNAGE**

My initial investigation has found the following deficiencies:

At the bottom of the steps leading from John Street. There is no sign indicating that you should turn left and go over the bridge to get back on the Trail.

There is no signage at the Bovaird Bridge on the North side that it is indeed Bovaird.

The signage at the bridge on the North of Loafers Lake is so small that it is hard to read from a bicycle.

The signage at the split of the Trail going North and the trail leading over to Colonel Bertram Drive is too small to be read from a bicycle.

Many other signs could also be increased in size. However these were the two that I had difficulty with.

George Shepperdley March 2015